

# TECHNICAL BULLETIN INDEX

THE ATA/CHAP. REF. COLUMN INDICATES THE MAINTENANCE AND/OR OVERHAUL MANUAL CHAPTER/S AFFECTED BY THE RESPECTIVE BULLETIN; OR, THE BULLETIN IS APPLICABLE TO A SERVICE INSTRUCTION (S.I.).

#### PROPRIETARY RIGHTS NOTICE

These data are proprietary to Bell Helicopter Textron, Inc. Disclosure, reproduction, or use of these data for any purpose other than helicopter operation is forbidden without prior written authorization from Bell Helicopter Textron, Inc.

Newly released Technical Bulletins can be viewed and printed by accessing our Service Directives website at <a href="https://www.bellcustomer.com">www.bellcustomer.com</a>. This publication supersedes BHT-47-TB INDEX dated 1 January 2007 in its entirety.

COPYRIGHT NOTICE

COPYRIGHT 2008

BELL ® HELICOPTER TEXTRON INC.

AND BELL HELICOPTER TEXTRON

CANADA LTD.

ALL RIGHTS RESERVED




A Textron Company

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

## **47 TECHNICAL BULLETIN INDEX**

## STATUS CODE



## ATA/CHAP

NUMBER	ISSUE	DATE	STATUS	REF.	SUBJECT
47-04-73-1	Basic	5-29-73			Main Rotor Mast Bearing
47-04-73-2	Basic	8-28-73			Lubrication for Tail Rotor Gearbox
47-(04-2)-73-2	Basic	12-19-73			Adjustment of Stabilizer Bar Assembly and Alignment of Fore and Aft and Lateral Control Power Cylinders
47-05-73-1	Basic	5-3-73			Daily Inspection of Tail Rotor Blades, P/N 47-642-117
47-13-73-1	Basic	1-2-73			Technical Bulletins Will Replace Service Letters as of January 1973
47-13-73-2	Basic	3-27-73			Inspection of Airframe Dynamic Components
47-13-73-3	Basic	9-18-73			Fluorescent Penetrant Inspection
47-03-74-1	Basic Rev B	4-15-74 8-19-74			Instructions for Checking Pre- Coning of Engine Cooling Fan Assembly and Installation of Fan Bearings
47-04-74-1	Basic	5-14-74			Installation of Duplex Ball Bearings in Main Case of Transmission
47-04-74-2	Basic	11-20-74			Installation of Transmission Fan Quill Sleeve, P/N 47-620-538-7

# **BHT-47-TB INDEX**

# **47 TECHNICAL BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
HOMBEN	IOOOL	DAIL	SIAIOO	IXEI .	3083201
47-75-1	Basic	2-24-75			Removal of Dynamic Stop Cables and Rework of Bearing Caps
47-75-2	Basic Rev A	3-3-75 5-3-76			Replacement of Current Fan Belt Sets
47-75-3	Basic	7-21-75			Exchange, Overhaul or Repair of Model 47 Hydraulic Cylinder Assembly and Irreversible Valves
47-75-4	Basic Rev A	12-15-75 4-9-92			Installation of Duplex Ball Bearings in Main Case of Transmission
47-76-1	Basic	4-8-76			Warranty Claim and Return of Parts
47-79-2	Basic	10-24-79			Rework of Tail Rotor Trunnion Bearing Housing, P/N 47-641-192- 1, to Add Second Grease Fitting
47-80-3	Basic	11-24-80			Stabilizer Bar Damper Frame Clamp, P/N 47-140-134-001, Inspection and Rework of
47-81-4	Basic	5-7-81			Approval of Alternate Lubricating Oil
47-83-5	Basic	8-11-83			Limits for Trimming Laminate Tips on Metal Main Rotor Blades, P/N 47-110-250 (All Dash Numbers), Revision of
47-84-6	Basic	9-11-84			Exchange Program for Clutch Shoes, P/N 47-620-610, 47-620- 670, and 47-620-694 (All Dash Numbers)
47-85-7	Basic	12-2-85			Tail Rotor Blade, P/N 047-642- 117-001, Improved Visibility Paint Scheme
47-88-8	Basic	2-8-88			Addition of Identification Decal of Aircraft Exterior
47-01-09	Basic	7-17-01			Main Rotor Grips 047-120-252- 115/047-120-135-107 and Adapter 047-120-183-103 Introduction of

#### **NOTICE**

The following blank pages are provided for entry of additional bulletins when distributed. These additional bulletins will be included in this index at next revision.

ATA/CHAP
NUMBER ISSUE DATE STATUS REF. SUBJECT

## **BHT-47-TB INDEX**

### **NOTICE**

The following blank pages are provided for entry of additional bulletins when distributed. These additional bulletins will be included in this index at next revision.

ATA/CHAP

NUMBER ISSUE DATE STATUS REF. SUBJECT