

Bell Helicopter **TEXTRON**

Bell Helicopter Textron
Division of Textron Inc.

Post Office Box 482
Fort Worth, Texas 76101
(817) 380 2011

OPERATIONS SAFETY NOTICE


31 AUGUST 1976

OSN 47-77-1

TO: ALL MODEL 47 OPERATORS
SUBJECT: ACCOMPLISHMENT OF S.B. 47-77-1

IN FEBRUARY 1977 BHT ISSUED SERVICE BULLETIN 47-77-1. ACCOMPLISHMENT OF THE BULLETIN REQUIRED THAT DUPLEX BEARING P/N47-620-629-7 BE INSTALLED AND INPUT PINION SHAFT P/N 47-645-205-3 BE VISUAL AND DIMENSIONALLY INSPECTED BEFORE 1 MARCH 1977.

AS OF THIS DATE OUR RECORDS REVEAL THAT 377 GEARBOXES STILL REMAIN TO BE INSPECTED. WE URGE THOSE WHO HAVE NOT ACCOMPLISHED S.B. 47-77-1 DO SO IMMEDIATELY.


THOMAS K. FLEMING
MANAGER
PRODUCT SUPPORT ENGINEERING