

# Bell Helicopter **TEXTRON**

Bell Helicopter Textron Inc.  
A Subsidiary of Textron Inc.

Post Office Box 482  
Fort Worth, Texas 76101  
(817) 280-2011

## **OPERATIONS SAFETY NOTICE**

18 JULY 1986

OSN 47-86-7

TO: OWNERS/OPERATORS OF ALL MODEL 47G,G-2,G-2A,G-2A-1,  
G-3,G-3B,G-3B-1,G-3B-2,G-3B-2A,G-4,G-4A,G-5,G-5A,  
J,J-2,AND J-2A.

SUBJECT: ACCOMPLISHMENT OF SERVICE BULLETINS 47-76-6 AND  
47-78-1.

THIS IS A REMINDER THAT THE MODEL 47 HELICOPTERS (47G,G-2A,G-2A-1,G-3,G-3B,G-3B-1,G-3B-2,G-3B-2A,G-4,G-4A,G-5,G-5A, J,J-2 AND J-2A) HAVE AN IMPROVED CRASHWORTHY FUEL SYSTEM THE INSTALLATION OF WHICH IS REQUIRED BY SERVICE BULLETINS 47-76-6 DATED 12-1-76 AND 47-78-1 DATED 4-4-78. THIS CRASHWORTHY FUEL SYSTEM PROVIDES WRAPPED FUEL TANKS AND BREAKAWAY FITTINGS FOR THE VENT, DRAIN AND CROSSOVER FUEL LINES ON THESE HELICOPTERS. BREAKAWAY FITTINGS FOR CROSSOVER FUEL LINES ARE PROVIDED FOR THE MODEL 47J SERIES HELICOPTERS.

BELL HELICOPTER TEXTRON,INC., IN THE INTEREST OF SAFETY, STRONGLY URGE ALL OPERATORS THAT HAVE NOT COMPLIED WITH SERVICE BULLETINS 47-76-6 AND 47-78-1 TO COMPLY IMMEDIATELY.

KITS AND/OR PARTS MAY BE ORDERED FROM YOUR NORMAL BHTI SPARES OUTLET. REFER TO SERVICE INSTRUCTIONS 435,436 OR 437 FOR KITS AND/OR PARTS REQUIRED FOR YOUR PARTICULAR MODEL(S).