

Bell Helicopter **TEXTRON**

Division of Textron Inc.

ILLUSTRATED PARTS BREAKDOWN MANUAL

TEMPORARY REVISION 47-80-2

MODEL 47G-5 and 47G-5A

REFERENCE: Alert Service Bulletin 47-80-6

This Temporary Revision issued to replace 47-620-605-1 bearing with an improved bearing.

INSERT THIS PAGE FACING PAGE 4-11

NOTE: This Temporary Revision will remain in effect until revised or incorporated in manual.

MODELS 47G-5 AND 47G-5A

ILLUSTRATED PARTS BREAKDOWN

SECTION IV TRANSMISSION

FIGURE & INDEX NUMBER	PART NUMBER	DESCRIPTION	UNITS PER ASSY.	MODELS USABLE ON				NON PROC-URABLE
				G 5	G 5A			
		1234567						
14 - 19	47-620-605-1	.BEARING (PRE SB 47-80-6)..... (RPL BY 47-620-929-1)	1	X	X			
	47-620-929-1	.BEARING (POST SB 47-80-6)..... (REPLACES 47-620-605-1)	1	X	X			